ALUMETRONTM

COVERAGE: 250SQ. FT. ONE COAT (16OZ BOTTLE), 2000SQ. FT. ONE COAT (1US GAL JUG)



ALUMETRON™ is an smooth to use clean polymer coating that bonds chemically and robotically to aluminum for a smooth, durable, defensive end that resists environmental harm and attachment of dirt. It continues your aluminum searching bright and new all season despite steady water immersion.

DIRECTIONS

PREPARATION:

New Aluminum: Clean & degrease aluminum. Wet aluminum with water, spray BOAT CLEAN PLUS™ onto floor andwash with a MARINE POWER MITT™, fabric, sponge, or strain washer. Hot water improves cleansing. Rinse and dry.

Fouled Aluminum: Remove fouling from aluminum with ALGEX™. Clean & degrease as above.

Tarnished Aluminum: Remove oxidation and stains with ALUMABRITE CBX®. Clean & degrease as above.

COVERAGE:

450ml / 16oz- 250 ft² 3.8L / 1US gal – 2,000 ft²

Source: www.auroramarine.com

APPLICATION:

Surface ought to be easy and dry.

WIPE:

Apply four skinny coats ALUMETRON™. Wipe on with a lint loose fabric pad, in long, even, overlapping strokes. Do now no longer overwork utility or bubbles and streaking will result.

CURE TIME at 77°F - 50% R.H.:

- To contact 10 min.
- To recoat 20 min.
- To mild carrier eight hrs.
- To complete treatment forty eight hrs.
- To water immersion ninety six hrs.
- To utility of VS721 ninety six hrs.

APPLICATION TEMPERATURE

15°C - 35°C

60°F - 95°F

HUMIDITY:

<80% RH<

CLEAN UP:

Soap & Water. Cured ALUMETRON™ may be eliminated with lacquer thinners.

DAMAGE REPAIR:

Repair scratched or abraded floor through cleansing broken location as above and practice four skinny coats of ALUMETRON™ with a folded fabric pad.

Source: www.auroramarine.com

WATER IMMERSION:

To guard surfaces with the intention to be constantly submerged, practice 2 coats VS721 BOTTOM COAT™ to completely cured regions beneath the waterline. Coating the whole hull or pontoon with VS721™ reduces abrasion harm, makes cleansing and preservation easier, reduces salt attachment and multiplied sturdiness and longevity.

SAFETY:

Wear protection glasses and guard pores and skin from immoderate exposure. If splashed in eyes, rinse with water for 10 minutes. If on pores and skin, wash with cleaning soap and water.