

# ALGEX™

**ALGEX™ REMOVES ALGAE, ZEBRA MUSSELS, BARNACLES.  
FOAMING ACTION ENSURES EVEN COVERAGE.**



## **DIRECTIONS:**

**Algae:** Use a brush or electric washing machine to remove loose growth. Spray the foam on the algae to make sure the surface is soaked. Do not spray on bare aluminum. Allow to work until the algae is easily released from the aluminum. Strongly wash or scrub and rinse. Repeat if necessary. Do not allow ALGEX™ to dry before rinsing.

**Barnacles and mussels:** Remove algae as described above. Spray the foam on the barnacles and mussels and let them work for 30 to 60 minutes. ALGEX™ will soften the shell and make scraping easier. Scrape it off with a wooden or plastic scraper. Spray the foam onto the adhesive and ring. Allow 30 to 60 minutes of work. Scrape off the residue. Rinse well. Repeat if necessary. Do not spray ALGEX™ onto bare aluminum.

**Calcium:** Not suitable for removing calcium deposits. If aluminum is contaminated or oxidized, use ALUMABRITE CBX® to clean and brighten it. Use ALUMABUFF™ to remove streaks and white clouds to maintain gloss. If the float is etched or striped polished by ALUMABUFF™. Use ALUMETRON™ for protection. In order to reduce the adhesion of dirt and make subsequent cleaning easier, please apply VS721™ on ALUMETRON™.

**Don't freeze**