BLACK STREAK REMOVER[™]



• EASILY REMOVES STUBBORN BLACK STREAKS FROM FIBERGLASS, ALUMINUM, PAINTED BOATS, R.V.'S AND TRUCKS

DIRECTIONS:

Wet special MARINE POWER MITT^m with water and squeeze out excess water. Apply BLACK STREAK REMOVER^m to MARINE POWER MITT^m. Start at top and work down. Wipe away black streaks and rinse clean. Dry with Boat Chamois.

Apply protective coat of PREMIUM BOAT SHINE™ to seal surface and make black streaks easier to remove.

DO NOT FREEZE
SHAKE WELL BEFORE USING

WARNING:

HARMFUL IF SWALLOWED.

FIRST AID TREATMENT:

Contains Pine Oil.

If swallowed, give one cup of milk or water.

SEEK MEDICAL AID.

Source: www.auroramarine.com